

# Contents

|           |                                      |    |
|-----------|--------------------------------------|----|
| <b>I</b>  | <b>Introduction</b>                  | 1  |
| <b>1</b>  | <b>Introduction</b>                  | 3  |
| <b>2</b>  | <b>The Extrusion Line</b>            | 5  |
| 2.1       | The Extruder                         | 5  |
| 2.2       | Pumping                              | 6  |
| 2.2.1     | The Path the Plastic Takes           | 7  |
| 2.2.2     | The Gear Box – RPM                   | 8  |
| 2.3       | Safety                               | 9  |
| <b>II</b> | <b>Control of the Machine</b>        | 11 |
| <b>3</b>  | <b>The Concepts of Total Control</b> | 13 |
| 3.1       | Overview                             | 13 |
| 3.1.1     | Sheet Extrusion                      | 15 |
| 3.1.2     | Blown Film Extrusion                 | 16 |
| 3.1.3     | Wire Extrusion Coating               | 16 |
| 3.1.4     | Foam Extrusion                       | 16 |
| 3.1.5     | Coextrusion                          | 17 |
| 3.1.6     | Alternate Polymer Extrusion          | 17 |
| 3.1.7     | “Lights-Out” Extrusion Systems       | 17 |
| 3.2       | Total Control                        | 18 |
| 3.3       | Aspects of Control                   | 19 |
| 3.3.1     | Machine Control                      | 19 |
| 3.3.2     | Process Control                      | 19 |
| 3.3.3     | Product Control                      | 19 |
| 3.3.4     | Plant-Wide Control                   | 20 |
| 3.3.5     | Statistical Quality Control          | 20 |

|          |  |    |
|----------|--|----|
| <b>4</b> | <b>Control of Temperature</b>                      | 21 |
| 4.1      | The Real World                                     | 23 |
| 4.2      | Temperature Controllers                            | 24 |
| 4.2.1    | On/Off Controls                                    | 25 |
| 4.2.2    | Simple Proportional Controller                     | 26 |
| 4.2.3    | Proportional Plus Automatic Reset Controllers      | 28 |
| 4.2.3.1  | Proportional Plus Automatic Reset Plus Rate        | 29 |
| 4.2.3.2  | Adjustment of 3-Mode Controllers                   | 30 |
| 4.2.3.3  | Automatic Trim                                     | 30 |
| 4.2.4    | Fuzzy Logic  | 31 |
| 4.3      | Sensing of Temperature                             | 31 |
| 4.3.1    | Placement of Temperature Sensors                   | 31 |
| 4.3.2    | Dual Sensing                                       | 32 |
| 4.3.3    | Types of Sensors                                   | 33 |
| 4.3.3.1  | Theory of Operation                                | 33 |
| 4.3.3.2  | Advantages of the Platinum Resistance Sensor       | 35 |
| 4.4      | Control of Heating and Cooling Power               | 41 |
| 4.4.1    | Mechanical Contactors                              | 41 |
| 4.4.2    | Mercury Contactors                                 | 41 |
| 4.4.3    | Solid State Contactors                             | 42 |
| 4.4.4    | Phase Control – True Proportional Control of Power | 42 |
| 4.4.5    | RFI-Free Solid State Power Modules                 | 44 |
| <b>5</b> | <b>Control of RPM</b>                              | 45 |
| 5.1      | Brush Type D-C Motors and Drives                   | 46 |
| 5.1.1    | How Does a Motor Work?                             | 47 |
| 5.1.2    | Drives for D-C Brush Type Motors                   | 49 |
| 5.1.3    | Net Excitation Voltage                             | 50 |
| 5.1.4    | Field Excitation                                   | 51 |
| 5.1.5    | Accuracy   | 52 |
| 5.1.6    | Synchronization of Multiple Motors                 | 53 |
| 5.2      | Vector Drives                                      | 54 |
| 5.2.1    | The Motor  | 55 |
| 5.2.2    | Flux Vector Drives                                 | 56 |

|            |   |    |
|------------|---|----|
| <b>III</b> | <b>Control of the Process</b> .....   | 57 |
| <b>6</b>   | <b>Control of the Plastic</b> .....   | 59 |
| 6.1        | Measurement and Control of the Quantity of Plastic<br>Passing Through the Die ..... | 60 |
| 6.1.1      | Don't Be a Luddite! .....   | 60 |
| 6.2        | When and Why Should a Melt Pump Be Used? .....                                      | 61 |
| 6.3        | Stabilizing the Throughput .....  | 65 |
| 6.4        | Microprocessor Melt Pump Control .....  | 66 |
| 6.5        | Other Advantages of Using a Melt Pump .....   | 69 |
| 6.6        | Measurement and Control of Melt Pressure .....                                      | 70 |
| 6.7        | Measurement and Control of Melt Temperature .....                                   | 71 |
| 6.8        | Measurement and Control of Viscosity – The Final Frontier! .....                    | 73 |
| 6.8.1      | Precise Measurement of Viscosity .....  | 74 |
| 6.9        | Summary .....   | 75 |
| <b>IV</b>  | <b>Control of the Final Product</b> .....   | 77 |
| <b>7</b>   | <b>Sheet Extrusion</b> .....  | 79 |
| 7.1        | Materials, Machines, and Applications .....   | 79 |
| 7.1.1      | The Die .....   | 81 |
| 7.1.2      | The Roll Stack .....  | 82 |
| 7.1.3      | Measurement of Thickness .....  | 83 |
| 7.1.3.1    | Beta Gauges .....   | 83 |
| 7.1.3.2    | Gamma Gauges .....  | 83 |
| 7.1.3.3    | Comparison .....  | 84 |
| 7.1.3.4    | The Traverse .....  | 85 |
| 7.2        | Automated Profile Control .....   | 86 |
| 7.3        | Coextrusion .....   | 87 |
| 7.3.1      | Feed Block Dies .....   | 88 |
| 7.3.2      | Multi-Manifold Dies .....   | 89 |
| <b>8</b>   | <b>Tubing</b> .....   | 91 |
| 8.1        | The Extruder .....  | 92 |
| 8.2        | Free-Air Extrusion .....  | 93 |
| 8.2.1      | The In-Line Die .....   | 93 |
| 8.2.2      | Crosshead Dies .....  | 94 |
| 8.3        | Cooling the Tubing – the Water Bath .....   | 95 |

---

|          |  |            |
|----------|--|------------|
| 8.4      | Vacuum Sizing .....  | 96         |
| 8.4.1    | The Die .....  | 96         |
| 8.4.2    | The Vacuum Sizing Chamber .....                                      | 96         |
| 8.4.3    | The Vacuum Pump .....  | 97         |
| 8.5      | The Cutter .....   | 98         |
| 8.6      | Measuring Product Parameters .....                                   | 99         |
| 8.6.1    | The Outside Diameter .....   | 99         |
| 8.6.2    | Measurement of the Inner Diameter by Calculation .....               | 99         |
| 8.6.3    | Measurement of the Inner Diameter by Ultrasonic<br>Gauging .....     | 100        |
| 8.6.4    | Measurement of Concentricity .....                                   | 100        |
| 8.6.5    | How Can Outer and Inner Diameter Be Varied? .....                    | 101        |
| 8.6.6    | Automated Control of the Outer Diameter .....                        | 102        |
| 8.6.7    | Automated Control of the Inner Diameter .....                        | 102        |
| 8.6.8    | Combined Automated Control .....                                     | 102        |
| 8.7      | Multi-Lumen Tubing .....   | 103        |
| 8.8      | “Bump” Tubing .....  | 103        |
| 8.9      | Alternate Polymer System .....                                       | 104        |
| 8.10     | Control of Length – The Puller .....                                 | 105        |
| 8.10.1   | Caterpillar Belt versus Rollers .....                                | 105        |
| 8.11     | Control of Puller Motor RPM .....                                    | 106        |
| 8.12     | Coextrusion .....  | 107        |
| 8.12.1   | Special Considerations for Medical Tubing Applications ....          | 108        |
| 8.12.1.1 | The Water Bath .....   | 108        |
| 8.12.1.2 | Air Supplies for Inside the Tube .....                               | 109        |
| 8.12.1.3 | Air Supplies for the Air Knife .....                                 | 109        |
| 8.12.1.4 | Air Supplies to the Classifying Conveyor .....                       | 110        |
| 8.13     | Integrated System Control .....                                      | 110        |
| <b>9</b> | <b>Other Types of Extruded Products .....</b>                        | <b>113</b> |
| 9.1      | Blown Film Extrusion .....   | 113        |
| 9.1.1    | Control of Thickness in the Cross-Machine Direction .....            | 113        |
| 9.1.2    | Control of Average Sheet Thickness in the Machine<br>Direction ..... | 114        |
| 9.1.3    | Measurement of Bubble Thickness .....                                | 114        |
| 9.1.4    | Advantages of Using a Melt Pump .....                                | 115        |
| 9.2      | Wire Coating Extrusion .....   | 115        |
| 9.2.1    | Wire Coating with Foam Insulation .....                              | 116        |
| 9.2.2    | Coextruded Wire Coating .....  | 117        |

|                               |   |            |
|-------------------------------|---|------------|
| 9.3                           | Fiber Optics Extrusion .....                              | 117        |
| 9.4                           | Profile Extrusion .....                                   | 118        |
| <b>10</b>                     | <b>Unattended Operation .....</b>                         | <b>121</b> |
| <b>V</b>                      | <b>Plant-Wide Control .....</b>                           | <b>123</b> |
| <b>11</b>                     | <b>Plant-Wide Control and Management .....</b>            | <b>125</b> |
| 11.1                          | The Report Program .....                                  | 126        |
| 11.1.1                        | The Time Machine .....                                    | 126        |
| 11.2                          | Run Sheets and Recipe Storage .....                       | 127        |
| 11.3                          | The Alarm Log Viewer .....                                | 128        |
| 11.4                          | Statistical Quality Control .....                         | 128        |
| <b>VI</b>                     | <b>Overall SQC .....</b>                                  | <b>131</b> |
| <b>12</b>                     | <b>Statistical Quality Control .....</b>                  | <b>133</b> |
| 12.1                          | Acceptable Quality Level – AQL .....                      | 133        |
| 12.2                          | Strip Chart Recorders .....                               | 135        |
| 12.3                          | What Was Deming Teaching? .....                           | 135        |
| 12.4                          | Deming Goes to Japan .....                                | 136        |
| 12.5                          | Quality Measurement – $\bar{X}$ and $\sigma$ .....        | 137        |
| 12.6                          | Numerical Analysis .....                                  | 139        |
| 12.7                          | How Many Measurements? .....                              | 140        |
| 12.8                          | How Much Faith Can We Put in the Measurements? .....      | 141        |
| 12.9                          | Make Sure You Are Measuring What You Think You Are! ..... | 142        |
| 12.10                         | Significance .....  | 143        |
| 12.11                         | Control Charts .....                                      | 143        |
| 12.12                         | $\sigma$ vs. “R” and Optimum Size of Sample .....         | 145        |
| 12.13                         | Statistical Quality Control Since Deming .....            | 146        |
| 12.14                         | The Larger Picture .....                                  | 148        |
| <b>Index</b> .....            |   | <b>149</b> |
| <b>About the Author</b> ..... |   | <b>155</b> |