

# Table of Contents

<b>Preface .....</b>	<b>V</b>
<b>Table of Contents .....</b>	<b>VII</b>
<b>Standards for Thermal Analysis.....</b>	<b>XIV</b>
<b>Abbreviations Used.....</b>	<b>XXI</b>
<b>Abbreviations for Plastics .....</b>	<b>XXVI</b>
<b>1 Differential Scanning Calorimetry (DSC).....</b>	<b>1</b>
1.1 Principles of DSC .....	1
1.1.1 Introduction.....	1
1.1.2 Measuring Principle .....	2
1.1.3 Procedure and Influential Factors .....	6
1.1.4 Evaluation .....	7
1.1.4.1 Glass Transition.....	7
1.1.4.2 Melting .....	10
1.1.4.3 Crystallization.....	16
1.1.4.4 Chemical Reaction — Dynamic Process .....	20
1.1.4.5 Specific Heat Capacity.....	21
1.1.4.6 Test Report .....	22
1.1.5 Calibration.....	22
1.1.5.1 Temperature Calibration .....	23
1.1.5.2 Energy Calibration (Enthalpy Calibration) .....	25
1.1.5.3 Heat-Flux Calibration by Means of Known Heat Capacity .....	25
1.1.6 Temperature-Modulated DSC (TMDSC).....	26
1.1.7 Overview of Practical Applications .....	30
1.2 Procedure .....	32
1.2.1 In a Nutshell.....	32
1.2.2 Influential Factors and Possible Errors During Measurement.....	34
1.2.2.1 Specimen Preparation .....	34
1.2.2.2 Specimen Mass .....	41

1.2.2.3	Pan .....	44
1.2.2.4	Purge Gas.....	47
1.2.2.5	Measuring Program .....	48
1.2.2.6	Evaluation.....	58
1.2.3	Real-Life Examples.....	63
1.2.3.1	Identification of Plastics .....	63
1.2.3.2	Crystallinity .....	66
1.2.3.3	Thermal History.....	67
1.2.3.4	Water Uptake.....	75
1.2.3.5	Nucleation.....	76
1.2.3.6	Aging .....	78
1.2.3.7	Crosslinking of Thermoplastics .....	82
1.2.3.8	Mixtures, Blends, and Contaminants .....	84
1.2.3.9	Curing of Thermosets .....	92
1.2.3.10	Results of Round-Robin Trials .....	98
1.2.3.11	Compiling TTT Diagrams .....	100
1.2.3.12	Examples of Temperature-Modulated DSC (TMDSC).....	102
1.3	References.....	105
<b>2</b>	<b>Oxidative Induction Time/Temperature (OIT).....</b>	<b>111</b>
2.1	Principles of OIT.....	111
2.1.1	Introduction.....	111
2.1.2	Measuring Principle .....	112
2.1.3	Procedure and Influential Factors .....	113
2.1.4	Evaluation .....	114
2.1.4.1	Dynamic Method .....	114
2.1.4.2	Static Method.....	115
2.1.4.3	Test Report .....	116
2.1.5	Overview of Practical Applications .....	116
2.2	Procedure .....	118
2.2.1	In a Nutshell.....	118
2.2.2	Influential Factors and Possible Errors During Measurement.....	119
2.2.2.1	Specimen Preparation .....	119
2.2.2.2	Specimen Mass .....	122
2.2.2.3	Pans .....	123
2.2.2.4	Purge Gas.....	123
2.2.2.5	Measuring Program .....	125
2.2.2.6	Evaluation.....	128

---

2.2.3	Real-Life Examples.....	131
2.2.3.1	Comparison of “Static” and “Dynamic” Methods .....	131
2.2.3.2	Influence of the Processing Parameters .....	132
2.2.3.3	Stabilizer Degradation Through Repeated Processing.....	133
2.2.3.4	Stabilizer Degradation Due to Effects of Media .....	135
2.2.3.5	Results of Round-Robin Trials .....	135
2.3	References.....	136
<b>3</b>	<b>Thermogravimetry (TG) .....</b>	<b>139</b>
3.1	Principles of TG.....	139
3.1.1	Introduction.....	139
3.1.2	Measuring Principle .....	139
3.1.3	Procedure and Influential Factors .....	140
3.1.4	Evaluation .....	141
3.1.4.1	Single-Step Change of Mass .....	141
3.1.4.2	Multistep Change of Mass .....	143
3.1.4.3	Test Report .....	145
3.1.5	Calibration.....	146
3.1.5.1	Buoyancy Correction .....	146
3.1.5.2	Mass Calibration .....	146
3.1.5.3	Temperature Calibration .....	146
3.1.6	Overview of Practical Applications .....	148
3.2	Procedure .....	150
3.2.1	In a Nutshell .....	150
3.2.2	Influential Factors and Possible Errors During Measurement.....	151
3.2.2.1	Specimen Preparation .....	151
3.2.2.2	Specimen Mass .....	153
3.2.2.3	Pan .....	154
3.2.2.4	Purge Gas.....	155
3.2.2.5	Measuring Program .....	157
3.2.2.6	Evaluation.....	159
3.2.3	Real-Life Examples.....	160
3.2.3.1	Carbon Black Content.....	160
3.2.3.2	Calcium Carbonate/Talc Fillers .....	162
3.2.3.3	Stabilizer Degradation .....	163
3.2.3.4	Repeated Processing .....	164
3.2.3.5	Multistep Decomposition.....	164
3.2.3.6	Media Effects.....	166

3.2.3.7	Degradation of Polyoxymethylene.....	168
3.2.3.8	Results of Round-Robin Trials .....	168
3.3	References.....	170
<b>4</b>	<b>Thermomechanical Analysis (TMA) .....</b>	<b>172</b>
4.1	Principles of TMA .....	172
4.1.1	Introduction.....	172
4.1.2	Measuring Principle .....	174
4.1.3	Procedure and Influential Factors .....	176
4.1.4	Evaluation .....	177
4.1.4.1	Coefficient of Linear Expansion.....	177
4.1.4.2	Glass Transition Temperature.....	178
4.1.4.3	Test Report .....	180
4.1.5	Calibration.....	180
4.1.5.1	Calibrating the Length .....	181
4.1.5.2	Calibrating the Temperature .....	181
4.1.6	Overview of Practical Applications .....	181
4.2	Procedure .....	183
4.2.1	In a Nutshell.....	183
4.2.2	Influential Factors and Possible Errors During Measurement.....	184
4.2.2.1	Specimen Preparation .....	184
4.2.2.2	Specimen Geometry.....	186
4.2.2.3	Probe.....	187
4.2.2.4	Applied Load .....	188
4.2.2.5	Measuring Program .....	192
4.2.2.6	Evaluation.....	193
4.2.3	Real-Life Examples.....	194
4.2.3.1	Thermal and Mechanical History.....	194
4.2.3.2	Influence of Conditioning .....	198
4.2.3.3	Influence of Aging.....	199
4.2.3.4	Curing of Thermosets, Postcuring .....	200
4.2.3.5	Influence of Fillers and Reinforcing Materials .....	201
4.2.3.6	Expansion and Shrinkage of Fibers and Film .....	204
4.2.3.7	Investigating Deformation .....	205
4.3	References.....	206

---

<b>5</b>	<b>pvT (pressure-volume-Temperature) Measurements</b> .....	<b>209</b>
5.1	Principles of pvT Measurements.....	209
5.1.1	Introduction.....	209
5.1.2	Measuring Principle.....	212
5.1.3	Procedure and Influential Factors.....	214
5.1.4	Evaluation.....	214
5.1.4.1	General Parameters Obtained with pvT Diagrams.....	214
5.1.4.2	Test Report.....	215
5.1.5	Calibration.....	215
5.1.5.1	Volume Calibration.....	215
5.1.5.2	Temperature Calibration.....	216
5.1.6	Overview of Practical Applications.....	216
5.2	Procedure.....	217
5.2.1	In a Nutshell.....	217
5.2.2	Influential Factors and Possible Errors During Measurement.....	218
5.2.2.1	Specimen Preparation.....	218
5.2.2.2	Specimen Mass.....	219
5.2.2.3	Seals.....	219
5.2.2.4	Measuring Program.....	219
5.2.2.5	Evaluation.....	222
5.2.2.6	Comparison with TMA.....	222
5.2.3	Real-Life Examples.....	223
5.2.3.1	Shrinkage During Cooling of Polymers.....	223
5.2.3.2	Shrinkage During Curing of UP Resin.....	225
5.2.3.3	Influence of Fillers on Shrinkage.....	226
5.2.3.4	Change in State During Injection Molding.....	229
5.2.3.5	Temperature Increase During Adiabatic Melt Compression.....	230
5.2.3.6	Temperature Increase During Curing of UP Resin.....	232
5.3	References.....	233
<b>6</b>	<b>Dynamic Mechanical Analysis (DMA)</b> .....	<b>236</b>
6.1	Principles of DMA.....	236
6.1.1	Introduction.....	236
6.1.2	Measuring Principle.....	240
6.1.2.1	Free Vibration.....	240
6.1.2.2	Forced Vibration (Non-resonant).....	240

6.1.3	Procedure and Influential Factors .....	243
6.1.4	Evaluation .....	243
6.1.4.1	Methods of Evaluating the Modulus Step .....	244
6.1.4.2	Evaluation of Peaks .....	247
6.1.4.3	Test Report .....	249
6.1.5	Calibration.....	250
6.1.5.1	Temperature Calibration.....	250
6.1.5.2	Modulus Calibration.....	251
6.1.5.3	Apparatus Calibration.....	251
6.1.6	Overview of Practical Applications .....	251
6.2	Procedure .....	253
6.2.1	In a Nutshell.....	253
6.2.2	Influential Factors and Possible Errors During Measurement.....	255
6.2.2.1	Mode of Deformation .....	255
6.2.2.2	Load Amplitude/Deformation.....	256
6.2.2.3	Test Arrangement/Specimen Geometry.....	257
6.2.2.4	Specimen Preparation/Clamping.....	264
6.2.2.5	Purge Gas.....	267
6.2.2.6	Measuring Program .....	267
6.2.2.7	T <sub>g</sub> -Evaluation.....	271
6.2.3	Real-Life Examples.....	276
6.2.3.1	DMA Curves for Various Polymers.....	276
6.2.3.2	Measurements on Polyamide .....	278
6.2.3.3	Conditioning – Water Content .....	280
6.2.3.4	Blends .....	282
6.2.3.5	Annealing .....	286
6.2.3.6	Curing of Reaction Resins .....	287
6.2.3.7	Aging .....	289
6.2.3.8	Influence of Plasticizers.....	291
6.2.3.9	Temperature Distribution in Fiber-Reinforced Polymers.....	291
6.3	References.....	294
<b>7</b>	<b>Micro-Thermal Analysis.....</b>	<b>300</b>
7.1	Principles of micro-TA .....	300
7.1.1	Introduction.....	300
7.1.2	Measuring Principle .....	300
7.1.3	Procedure and Influencing Factors.....	302
7.1.4	Evaluation .....	303

---

7.1.5	Calibration.....	304
7.1.6	Overview of Practical Applications .....	305
7.2	Procedure .....	306
7.2.1	In a Nutshell.....	306
7.2.2	Influential Factors and Possible Errors During Measurement.....	307
7.2.2.1	Specimen Preparation .....	307
7.2.2.2	Generating the Surface Image.....	308
7.2.2.3	Choice of Measuring Points.....	308
7.2.2.4	Load.....	309
7.2.2.5	Measuring Program .....	310
7.2.2.6	Evaluation.....	312
7.2.3	Real-Life Examples.....	312
7.2.3.1	Identification of Polymers .....	312
7.2.3.2	Boundary Layer of a PP Sample .....	313
7.2.3.3	Multilayer Pipe .....	315
7.2.3.4	Gating Region in a Two-Component Sample .....	315
7.2.3.5	PA 6 in a Metal Composite.....	317
7.2.3.6	Detection of Surface Aging .....	318
7.3	References.....	319
<b>8</b>	<b>Brief Characterization of Key Polymers.....</b>	<b>320</b>
<b>9</b>	<b>Subject Index.....</b>	<b>359</b>