

# HANSER

Table of Contents

Jordan Rotheiser

Joining of Plastics

Handbook for Designers and Engineers

ISBN: 978-3-446-40786-2

For further information and order see

<http://www.hanser.de/978-3-446-40786-2>  
or contact your bookseller.

# Contents

<b>1</b>	<b>Rapid Guidelines for Joining of Plastics and Efficient Use of This Handbook .....</b>	<b>1</b>
1.1	Efficient Use of This Handbook .....	1
1.2	Rapid Guidelines for Assembly of Plastics .....	2
1.2.1	Adhesives (Chapter 7).....	2
1.2.1.1	Liquids: Solvent-Based, Water-Based, and Anaerobic Adhesives .....	2
1.2.1.2	Mastics.....	3
1.2.1.3	Hot Melts .....	3
1.2.1.4	Pressure-Sensitive Adhesives .....	3
1.2.2	Fasteners and Inserts (Chapter 8).....	3
1.2.3	Hinges (Chapter 9).....	4
1.2.4	Hot Plate/Hot Die/Fusion and Hot Wire/Resistance Welding (Chapter 10) .....	4
1.2.5	Hot Gas Welding (Chapter 11) .....	5
1.2.6	Induction Welding (Chapter 12) .....	5
1.2.7	Insert Molding (Chapter 13) .....	5
1.2.8	Multipart Molding (Chapter 13) .....	6
1.2.9	Press Fits/Force Fits/Interference Fits/Shrink Fits (Chapter 14) .....	6
1.2.10	Solvent Joining (Chapter 7) .....	6
1.2.11	Snap Fits (Chapter 15) .....	7
1.2.12	Spin Welding (Chapter 16).....	7
1.2.13	Staking/Swaging/Peening/Cold Heading/Cold Forming (Chapter 17).....	7
1.2.14	Threads – Molded in (Chapter 18).....	8
1.2.15	Threads – Tapped (Chapter 18).....	8
1.2.16	Ultrasonic Welding (Chapter 19).....	8
1.2.17	Vibration Welding (Chapter 20).....	9
1.2.18	Welding with Lasers (Chapter 21).....	9
1.3	Assembly Methods Selection by Size.....	9
1.4	Assembly Methods Selection by Joining Time .....	11
<b>2</b>	<b>Designing for Efficient Assembly.....</b>	<b>12</b>
2.1	Avoiding Part Distortion.....	12
2.2	Inside Corner Stress .....	13
2.3	Ribs and Bosses .....	14
2.4	Draft.....	15
2.5	Shrinkage .....	17
2.6	Fitments .....	19
2.6.1	Drawing Conventions for Plastic Assembly .....	19
2.6.2	Importance of Tolerancing for Assembly .....	21
2.6.3	Special Drafting Practices for Plastics .....	22
2.6.4	Procedure for Establishing Tolerances .....	26
2.7	Design Practices for Looser Tolerances in Plastics .....	27
2.7.1	Three-Point Location .....	28

2.7.2	Hollow Bosses .....	28
2.7.3	Crush Ribs .....	30
2.7.4	Flexible Ribs .....	31
2.7.5	Inside/Outside Fitments .....	32
2.7.6	Step Fitments .....	32
2.8	More Relaxed Tolerances for Large Parts .....	33
2.8.1	Drill in Place .....	33
2.8.2	Oversize Hole with Washer .....	33
2.8.3	Criss Cross Slots .....	33
2.8.4	Separation of Functions .....	34
2.8.5	Corner Clearance .....	34
2.9	Semidovetail Joint .....	35
2.10	Minimizing the Effect of Misalignment on Appearance .....	36
2.11	The Plastic Product Design for Assembly Checklist .....	36
2.12	Testing .....	36
<b>3</b>	<b>Cost Reduction In Assembly .....</b>	<b>40</b>
3.1	Introduction .....	40
3.2	The Micro Approach to Part Reduction.....	40
3.2.1	Combining Parts Through Materials.....	41
3.2.2	Combining Parts Through Processes .....	42
3.3	The Macro Approach to Part Reduction.....	43
3.3.1	Multiple Material Processing .....	47
3.3.2	Coextrusion.....	48
3.3.3	Coinjection Molding.....	49
3.3.4	Multipart or Two-Color Injection Molding .....	49
3.4	Elimination of Fasteners .....	49
3.4.1	Multiple Parts per Fastener .....	50
3.4.2	Press and Snap Fits .....	50
3.4.3	Integral Hinges.....	51
3.4.4	Combining Fastener Elimination Concepts .....	51
3.5	Holistic Design .....	53
3.5.1	The Overall Design Considerations .....	53
3.5.2	The Thread Design.....	54
3.5.3	The Processing Considerations .....	55
3.5.4	The Tooling Considerations.....	55
3.5.5	Execution .....	56
3.5.6	Toward Holistic Design.....	56
<b>4</b>	<b>Design for Disassembly and Recycling.....</b>	<b>58</b>
4.1	Introduction .....	58
4.2	Design for Disassembly.....	59
4.2.1	Reopenable Assemblies.....	59
4.2.2	Permanent Assemblies.....	63
4.3	Design for Recycling .....	64
4.3.1	Simplification .....	65
4.3.2	Assembly Method Selection .....	65

4.3.2.1	Reopenable Methods .....	65
4.3.2.2	Permanent Methods .....	66
4.3.3	Material Selection .....	66
4.3.4	Additives .....	67
4.3.5	Contaminants .....	68
4.3.6	Material Reduction.....	68
4.3.7	Identification and Disassembly Instructions .....	70
<b>5</b>	<b>Assembly Method Selection by Material.....</b>	<b>71</b>
5.1	Thermoplastics Versus Thermosets .....	71
5.2	Amorphous Versus Semicrystalline Thermoplastics .....	72
5.2.1	Postmolding Shrinkage .....	73
5.2.2	Coefficient of Linear Thermal Expansion .....	73
5.2.3	Weldability.....	74
5.2.4	Solvent Sealability .....	74
5.3	Thermosets.....	74
5.4	Assembly Method by Material .....	75
5.4.1	Properties and Assembly-Related Data for Selected Materials .....	81
5.4.2	Adhesives.....	114
5.4.3	Using the SPI Tables.....	114
5.5	Material Databases.....	156
5.6	Material Suppliers.....	156
<b>6</b>	<b>Assembly Method Selection by Process.....</b>	<b>158</b>
6.1	Introduction.....	158
6.2	Blow Molding.....	158
6.2.1	The Process .....	158
6.2.2	Assembly Considerations.....	159
6.3	Casting, Potting, Encapsulation, and Embedment .....	160
6.3.1	The Processes.....	160
6.3.2	Assembly Considerations.....	161
6.4	Coextrusion.....	161
6.5	Co-Injection Molding .....	161
6.6	Cold Press Molding .....	161
6.6.1	The Process .....	161
6.6.2	Assembly Considerations.....	162
6.7	Compression Molding.....	162
6.7.1	The Process .....	162
6.7.2	BMC: Bulk Molding Compound .....	163
6.7.3	SMC: Sheet Molding Compound.....	163
6.7.4	Assembly Considerations.....	163
6.8	Extrusion.....	164
6.8.1	The Process .....	164
6.8.2	Coextrusion .....	165
6.8.3	Assembly Considerations.....	166
6.9	Filament Winding .....	167
6.9.1	The Process .....	167
6.9.2	Assembly Considerations.....	168

---

6.10 Gas-Assisted Injection Molding .....	168
6.11 Gas Counter Pressure Structural Foam Molding .....	168
6.12 Injection Molding .....	168
6.12.1 The Process .....	168
6.12.2 Assembly Considerations .....	169
6.13 Lay-up and Spray-up .....	170
6.13.1 The Processes .....	170
6.13.2 Assembly Considerations .....	170
6.14 Machining .....	171
6.14.1 The Process .....	171
6.14.2 Thermoplastics .....	172
6.14.3 Thermosets .....	172
6.14.4 Assembly Considerations .....	173
6.15 Pultrusion .....	173
6.15.1 The Process .....	173
6.15.2 Assembly Considerations .....	174
6.16 Reaction Injection Molding (RIM) .....	174
6.16.1 The Process .....	174
6.16.2 Assembly Considerations .....	175
6.17 Resin Transfer Molding (RTM) .....	176
6.17.1 The Process .....	176
6.17.2 Assembly Considerations .....	177
6.18 Rotational Molding .....	177
6.18.1 The Process .....	177
6.18.2 Assembly Considerations .....	179
6.19 Structural Foam Molding, Gas Counterpressure Structural Foam Molding, and Coinjection Molding .....	180
6.19.1 The Processes .....	180
6.19.2 Assembly Considerations .....	181
6.20 Thermoforming .....	183
6.20.1 The Processes .....	183
6.20.2 Thin-Gauge Thermoforming .....	184
6.20.3 Heavy-Gauge Thermoforming .....	184
6.20.4 Pressure Thermoforming .....	185
6.20.5 Other Forming Processes .....	185
6.20.6 Assembly Considerations .....	185
6.21 Twin-Sheet Thermoforming .....	186
6.21.1 The Process .....	186
6.21.2 Assembly Considerations .....	187
6.22 Transfer Molding .....	187
6.22.1 The Process .....	187
6.22.2 Assembly Considerations .....	188
6.23 Process Selection .....	188
6.23.1 Thermoplastic Open Shapes .....	190
6.23.2 Thermoset Open Shapes .....	191
6.23.3 Hollow Parts .....	192
6.23.4 Profiles .....	192
6.23.5 Ultra High Strength .....	193

<b>7</b>	<b>Adhesive and Solvent Joining .....</b>	<b>194</b>
7.1	Advantages and Disadvantages .....	194
7.1.1	Advantages.....	194
7.1.2	Disadvantages .....	196
7.2	Basic Theory and Terminology .....	197
7.3	Methods for Measuring the Wettability of a Plastic Surface .....	199
7.3.1	Contact Angle Test .....	199
7.3.2	Wetting Tension Test (ASTM D-2578-73, Wetting Tension of Polyethylene and Polypropylene Films).....	199
7.3.3	Adhesion Ratio Test (Tentative ASTM D-2141-63R).....	200
7.3.4	Water Spreading Test.....	200
7.3.5	Dye Stain Test.....	200
7.3.6	Ink Retention Test.....	200
7.4	Surface Treatments .....	201
7.4.1	Solvent Cleaning.....	202
7.4.1.1	Solvent Immersion.....	203
7.4.1.2	Solvent Wiping.....	203
7.4.1.3	Solvent Spray.....	203
7.4.1.4	Vapor Degreasing .....	203
7.4.1.5	Ultrasonic Vapor Degreasing .....	203
7.4.1.6	Ultrasonic Cleaning with Liquid Rinse .....	203
7.4.2	Abrasive Methods .....	203
7.4.2.1	Dry Abrasion .....	204
7.4.2.2	Dry Abrasive Blast .....	204
7.4.2.3	Wet Abrasive Blast.....	204
7.4.2.4	Wet Abrasive Scour.....	205
7.4.2.5	Detergent Scrub.....	205
7.4.3	Surface Energy Treatments and Process Selection Factors.....	205
7.4.3.1	Chemical Treatment .....	205
7.4.3.2	Corona Treatment .....	205
7.4.3.3	Plasma Treatment .....	207
7.4.3.4	Flame Treatment.....	207
7.4.3.5	Process Selection Factors .....	208
7.4.4	Shelf Life of Surface Treatments .....	208
7.5	Design for Adhesion .....	208
7.5.1	Shear Stress .....	209
7.5.2	Tensile Stress .....	209
7.5.3	Cleavage.....	209
7.5.4	Peel.....	210
7.5.5	Adhesive Joint Designs.....	210
7.5.5.1	Load-Bearing or Non-Load-Bearing Joints .....	210
7.5.5.2	Lap Joints.....	211
7.5.5.3	Butt Joints.....	216
7.5.5.4	Screw and Glue.....	219
7.6	Adhesives.....	219
7.6.1	Acrylics .....	226
7.6.2	Anaerobics .....	226
7.6.3	Cyanoacrylates.....	227

7.6.4	Epoxies .....	227
7.6.5	Hot Melts .....	228
7.6.6	Phenolics.....	228
7.6.7	Polyurethanes.....	229
7.6.8	Polysulfides.....	229
7.6.9	Pressure-Sensitive Adhesives .....	229
7.6.10	Silicones.....	230
7.6.11	Solvent-Based Adhesives .....	230
7.6.12	Water-Based Adhesives.....	230
7.7	Solvents .....	231
7.8	Adhesive and Solvent Assembly Techniques.....	233
7.8.1	Fixturing .....	233
7.8.2	Clamping.....	234
7.8.3	Application Methods.....	235
7.8.3.1	Capillary Method.....	235
7.8.3.2	Dip or Soak Method .....	236
7.9	Adhesive and Solvent System Selection.....	237
7.10	Glossary .....	239
7.11	Sources.....	241
<b>8</b>	<b>Fasteners and Inserts .....</b>	<b>244</b>
8.1	Advantages and Disadvantages .....	244
8.1.1	Advantages of Using Fasteners.....	244
8.1.2	Disadvantages of Using Fasteners .....	244
8.2	Basic Design Considerations for Fasteners .....	246
8.2.1	Creep Effects .....	246
8.2.2	Stress Relaxation Effects .....	247
8.2.3	Notch Sensitivity .....	247
8.2.4	Craze Resistance .....	248
8.2.5	Stiffness Considerations .....	249
8.2.6	Differentials in the Coefficients of Linear Thermal Expansion.....	249
8.2.7	Loss of Properties Due to Moisture .....	250
8.2.8	Clamp Load .....	250
8.2.8.1	Strain Method .....	250
8.2.8.2	Torque Method .....	251
8.2.9	Vibration Resistance .....	252
8.3	Methods of Using Fasteners with Plastics .....	252
8.3.1	Press-in Fasteners .....	253
8.3.2	Self-Tapping Screws.....	254
8.3.2.1	Strength of Plastic Threads.....	254
8.3.2.2	Thread-Forming and Thread-Cutting Screws.....	256
8.3.3	Special Screws for Plastics .....	259
8.3.3.1	Narrow Thread Forms .....	259
8.3.3.2	Alternating Thread Heights .....	259
8.3.3.3	Asymmetrical Thread Forms.....	259
8.4	Selection of Self-Tapping Screws .....	259
8.4.1	Cost Criteria.....	260
8.4.2	Fail/Drive Ratio and Differential.....	260

---

8.4.3	Strength Criteria.....	261
8.4.4	Thread Cutting or Thread Forming.....	262
8.4.5	Tapped or Molded-in Threads .....	262
8.5	Threaded Inserts: Advantages.....	263
8.6	Boss Cap .....	264
8.7	Helical Coil Inserts .....	264
8.8	Self-Tapping Inserts.....	265
8.9	Press-in Inserts .....	265
8.10	Glue-in Inserts .....	266
8.11	Expansion Inserts.....	266
8.12	Molded-in Inserts.....	267
8.13	Ultrasonic Inserts.....	267
8.14	Heat-Installed Inserts .....	270
8.15	Induction Inserts .....	271
8.16	Hermetic Seals .....	272
8.17	Studs .....	272
8.18	Insert Design Considerations .....	273
8.19	U- or J-Clips.....	273
8.20	Tee Nuts.....	274
8.21	Machine Screws.....	274
8.22	Tapping and Stud Plates .....	276
8.23	Plastic Screws .....	276
8.24	Screw Heads and Washers .....	277
8.25	Boss Designs.....	277
8.25.1	Design Criteria.....	277
8.25.2	Boss Sinks.....	278
8.25.2.1	Coring.....	278
8.25.2.2	Location.....	280
8.25.2.3	Support.....	280
8.25.2.4	Material.....	281
8.25.2.5	Surface Treatment.....	281
8.25.3	Weld Lines.....	281
8.26	Self-Threading Nuts.....	283
8.27	Twist Nuts.....	283
8.28	Press-on Nuts .....	283
8.29	Spring Clips .....	284
8.30	Push-in Fasteners.....	284
8.31	Rivets .....	284
8.32	Sources.....	286
8.32.1	Fasteners and Inserts.....	286
8.32.2	Threaded-Insert.....	287
8.32.3	Thermal Insertion Equipment .....	288
8.32.4	Induction Insertion Equipment .....	288
8.32.5	Ultrasonic Insertion Equipment.....	288
<b>9</b>	<b>Hinges.....</b>	<b>289</b>
9.1	Advantages and Disadvantages .....	289
9.1.1	Advantages.....	289



9.1.2	Disadvantages .....	289
9.2	One-Piece Integral Hinges .....	289
9.2.1	The Living Hinge .....	290
9.2.1.1	Living Hinge Design .....	291
9.2.1.2	Living Hinge Molding Considerations .....	294
9.2.1.3	Living Hinges by Other Processes .....	298
9.2.2	The Mira Spring Hinge .....	300
9.2.3	Standard Hinges .....	302
9.2.4	Tab Hinges .....	303
9.3	Two-Piece Plastic Hinges .....	303
9.3.1	Ball-and-Socket Hinges .....	304
9.3.2	Two-Piece Lug-and-Pin Hinges .....	304
9.3.3	Hook-and-Eye Hinges .....	305
9.4	Three-Piece Hinges .....	305
9.4.1	Three-Piece Lug and Pin .....	306
9.4.2	Piano Hinge .....	306
9.5	Latches .....	307
9.5.1	Snaps .....	307
9.5.2	Rathbun Spring .....	307
9.6	Number of Hinges and Location .....	307
<b>10</b>	<b>Hot Plate/Hot Die/Fusion and Hot Wire/Resistance Welding .....</b>	<b>308</b>
10.1	Advantages and Disadvantages .....	308
10.1.1	Description .....	308
10.1.2	Advantages .....	308
10.1.3	Disadvantages .....	309
10.2	Materials .....	310
10.3	The Process .....	311
10.4	Types of Hot Plate Welding .....	315
10.4.1	Low Temperature Hot Plate Welding .....	315
10.4.2	High Temperature Hot Plate Welding .....	315
10.4.3	Noncontact Hot Plate Welding .....	316
10.5	Hot Plate Welding Joint Designs .....	316
10.6	Equipment .....	318
10.7	Hot Wire/Resistance Welding .....	319
10.8	Sources .....	320
<b>11</b>	<b>Hot Gas Welding .....</b>	<b>321</b>
11.1	Advantages and Disadvantages .....	321
11.1.1	Advantages .....	321
11.1.2	Disadvantages .....	321
11.2	The Process .....	322
11.2.1	Tack Welding .....	322
11.2.2	Permanent Hot Gas Welding .....	323
11.2.3	High Speed Welding .....	324
11.2.4	Extrusion Welding .....	326
11.3	Joint Designs .....	326
11.4	Welding Practice .....	328

11.4.1 Appearance Problems .....	329
11.4.2 Cracking Problems.....	330
11.4.3 Distortion .....	330
11.4.4 Fusion Problems.....	330
11.4.5 Penetration .....	330
11.4.6 Porosity .....	331
11.4.7 Scorching .....	331
11.5 Testing the Weld.....	331
11.5.1 Nondestructive Testing.....	331
11.5.1.1 Visual Examination .....	331
11.5.1.2 Leak Tests.....	332
11.5.2 Destructive Tests.....	332
11.5.2.1 Tensile Test.....	332
11.5.2.2 Bending Test.....	332
11.5.2.3 Rod Removal Test .....	332
11.5.3 Chemical Test .....	332
11.5.4 Spark Test .....	333
11.6 Applications .....	333
11.7 Sources.....	333
11.7.1 Welding Rods.....	333
11.7.2 Welding Equipment .....	333
11.7.3 Welding Rod And Equipment.....	334

**12 Induction/Electromagnetic Welding..... 335**

12.1 Description.....	335
12.2 Advantages and Disadvantages .....	335
12.2.1 Advantages.....	335
12.2.2 Disadvantages .....	336
12.3 The Equipment.....	337
12.4 The Process.....	339
12.5 The Coil .....	340
12.5.1 Single-Turn Coils.....	340
12.5.2 Hairpin Coils.....	340
12.5.3 Multi-Turn Coils .....	341
12.5.4 Split Coils .....	341
12.5.5 Other Types of Coils.....	342
12.5.6 Coil Positioning .....	342
12.5.7 Flux Concentrators.....	343
12.6 Materials .....	343
12.6.1 Polymers .....	343
12.6.2 The Electromagnetic Material.....	343
12.6.2.1 Molded-in Pre-Forms .....	343
12.6.2.2 Hot Melt Electromagnetic Materials .....	344
12.6.2.3 Liquid Electromagnetic Materials .....	345
12.7 Joint Designs.....	345
12.8 Encapsulation.....	348
12.9 Film and Sheeting .....	348
12.9.1 Intermittent Sealing.....	348

12.9.2 Continuous Sealing .....	349
12.10 Inserting Metal into Plastic .....	349
12.11 Sources .....	350
<b>13 Insert and Multipart Molding.....</b>	<b>351</b>
13.1 Description.....	351
13.2 Insert Molding .....	351
13.2.1 Advantages of Insert Molding .....	351
13.2.2 Disadvantages of Insert Molding.....	352
13.2.3 Design with Threaded Inserts .....	353
13.2.4 Mold Considerations for Threaded Inserts .....	356
13.2.5 Custom-Designed Inserts .....	358
13.2.6 Outserts: Inserts Larger than the Moldment .....	362
13.2.7 Hermetic Seals .....	363
13.2.8 Preparation of Inserts .....	363
13.2.9 Decorative Inserts .....	364
13.3 Multi-Part Molding.....	366
13.3.1 Description.....	366
13.3.2 Advantages Particular to Multi-part Molding.....	366
13.3.3 Disadvantages Particular to Multi-part Molding .....	367
13.3.4 The Process.....	367
13.3.5 Materials .....	368
13.4 Sources.....	370
<b>14 Press Fits/Force Fits/ Interference Fits/Shrink Fits .....</b>	<b>372</b>
14.1 Advantages and Disadvantages .....	372
14.1.1 Advantages .....	372
14.1.2 Disadvantages .....	372
14.2 Press Fit Engineering.....	373
14.2.1 Engineering Notation.....	373
14.2.2 Geometric Factor .....	375
14.2.3 Changes Due to Temperature Variations.....	375
14.2.4 Hoop Stress.....	376
14.2.4.1 Metal Shaft in Plastic Boss.....	376
14.2.4.2 Shaft and Boss of Same Material .....	376
14.2.4.3 Shaft and Boss of Different Plastics .....	376
14.2.4.4 Quick Methods .....	377
14.2.5 Assembly and Disassembly Forces.....	377
14.2.6 Dimensional Changes Due to Assembly .....	378
14.2.7 Relationships.....	378
14.2.8 Equation Limitations.....	379
14.3 Safety Factor.....	384
14.4 Processing.....	384
14.5 Material Selection.....	385
14.6 Part Design .....	385
14.6.1 Heavy-Duty Press Fits .....	385
14.6.2 Light-Duty or Reopenable Press Fits.....	386
14.6.3 Other than Round.....	387

14.7 Case Studies.....	388
14.7.1 Determination of Changes in Diameter Due to Temperature Variations.....	388
14.7.2 The Geometric Factor for Use In Press Fit Equations .....	389
14.7.3 Determination of Design Stress and for a Metal Shaft in a Plastic Boss Maximum Allowable Interference for a Metal Shaft in a Plastic Boss.....	389
14.7.4 Dimensional Changes Due to Assembly.....	391
14.7.4.1 Metal Shaft in Plastic Boss.....	391
14.7.4.2 Plastic Shaft and Metal Boss .....	391
14.7.5 Determination of Design Stress and Maximum Allowable Interference for a Shaft and Boss of the Same Material.....	392
14.7.6 Determination of Design Stress and Maximum Allowable Interference for a Shaft and Boss of Different Plastics .....	393
14.7.7 Determination of Assembly and Disassembly Forces .....	395
14.7.8 Determination of Torsional Holding Capacity.....	395
<b>15 Snap Fits.....</b>	<b>396</b>
15.1 Advantages and Disadvantages .....	396
15.1.1 Advantages.....	396
15.1.2 Disadvantages .....	397
15.2 General Applications .....	398
15.3 General Engineering Principles .....	398
15.3.1 Allowable Dynamic Strain.....	398
15.3.2 Corner Stress Concentrations.....	399
15.3.3 Engineering Adjustments When Both Parts Are Elastic.....	400
15.3.4 Finite Element Analysis.....	401
15.4 Cantilever Snap Fits.....	401
15.4.1 Cantilever Snap Fit Designs.....	401
15.4.2 Cantilever Snap Fit Engineering.....	404
15.5 Cylindrical, Ring, Perimeter, or Annular Snap Fits.....	410
15.5.1 Cylindrical Snap Fit Designs .....	410
15.5.2 Engineering of Cylindrical, Ring, Perimeter, or Annular Snap Fits .....	412
15.5.2.1 Maximum Permissible Interference.....	412
15.5.2.2 Transverse and Axial Forces .....	412
15.6 Torsion Snap Fits .....	415
15.6.1 Torsion Snap Fit Designs.....	415
15.6.2 Engineering of Torsion Snap Fits .....	415
15.7 Strippable Snap Fits .....	417
15.8 The Injection Molding Process .....	418
15.9 Molds for Snap Fits.....	419
15.9.1 The Basics of Injection Mold Construction .....	419
15.9.2 Ejection and Cooling Systems for Stripping Molds.....	421
15.9.3 Cores for Nonstripping Molds .....	423
15.9.4 Snap Fit Details in the Mold Cavity .....	425
15.10 Conclusions .....	427
15.11 Case Studies .....	428
15.11.1 Cantilever Snap Fit Determination of Permissible Deflection.....	428
15.11.2 Cantilever Snap Fit Determination of Radial and Mating Forces.....	431

15.11.3 Annular Snap Fit Determination of Maximum Permissible Interference ...	432
15.11.4 Annular Snap Fit Determination of Maximum Design Strain .....	432
15.11.5 Annular Snap Fit Determination of Transverse and Axial Forces for a Snap Fitment Located Near the End of the Tube .....	433
15.11.6 Annular Snap Fit Determination of Transverse and Axial Forces for a Snap Fitment Located Remote From the End of the Tube .....	434
15.11.7 Self-locking Angle.....	435
<b>16 Spin Welding .....</b>	<b>436</b>
16.1 Description of Spin Welding .....	436
16.2 Advantages and Disadvantages of Spin Welding .....	436
16.2.1 Advantages .....	436
16.2.2 Disadvantages .....	437
16.3 Spin Welding Process .....	438
16.4 Materials .....	440
16.5 Design for Spin Welding .....	442
16.5.1 Overall Design Considerations .....	442
16.5.2 Joint Designs .....	442
16.6 The Equipment for Spin Welding .....	444
16.6.1 Drill-Press-Based Spin Welders .....	444
16.6.1.1 Tooling for Drill-Press-Based Inertial Welding .....	444
16.6.1.2 Tooling for Drill-Press-Based Pivot Tool Welding .....	445
16.6.2 Commercial Inertia Spin Welders.....	445
16.6.3 Commercial Direct-Drive Spin Welders.....	447
16.7 Sources .....	449
<b>17 Staking/Swaging/Peening/ Cold Heading/Cold Forming .....</b>	<b>450</b>
17.1 Advantages and Disadvantages of Staking/ Cold Forming .....	450
17.1.1 Advantages .....	450
17.1.2 Disadvantages .....	451
17.2 Staking .....	451
17.2.1 Cold Forming of Stakes .....	452
17.2.2 Hot Air/Cold Staking .....	454
17.2.3 Ultrasonic Cold Forming .....	455
17.2.4 Hot Die Forming of Stakes (Thermal Staking).....	457
17.2.5 Ultrasonic Hot Forming of Stakes .....	457
17.2.6 Laser Staking .....	458
17.3 Stake Design .....	458
17.3.1 The Stud.....	458
17.3.2 Stake Heads .....	459
17.4 Swaging .....	462
17.5 Sources.....	463
17.5.1 Thermal Staking.....	463
17.5.2 Hot Air/Cold Staking.....	464
17.5.3 Laser Staking .....	464
17.5.4 Ultrasonic.....	464

<b>18 Threads: Tapped and Molded-in</b> .....	465
18.1 Advantages and Disadvantages of Integral Threads .....	465
18.1.1 Advantages Common to Threads of Both Types .....	465
18.1.2 Disadvantages Common to Threads of Both Types .....	465
18.2 Drilled and Tapped Holes in Plastics .....	466
18.2.1 Advantages Unique to Tapped Threads .....	466
18.2.2 Disadvantages Unique to Tapped Threads .....	466
18.2.3 Drilling Holes in Plastics .....	467
18.2.4 Reaming Holes in Plastics .....	468
18.2.5 Tapping Holes in Plastics .....	468
18.3 Molded Threads in Plastics .....	471
18.3.1 Advantages Unique to Molded-in Threads .....	471
18.3.2 Disadvantages Unique to Molded-in Threads .....	471
18.3.3 Thread Design .....	471
18.3.4 Molds for Threads .....	473
18.3.4.1 Stripping Molds for Internal Threads .....	474
18.3.4.2 Collapsing Core Molds for Internal Threads .....	475
18.3.4.3 Expandable Cavity Molds for External Threads .....	477
18.3.4.4 Split-Cavity Molds for External Threads .....	477
18.3.4.5 Unscrewing Molds for Internal Threads .....	479
18.3.4.6 Unscrewing Chuck Plate Mold .....	479
18.3.4.7 Molds for Parts with Less than One Turn of Thread .....	479
18.4 Sources .....	480
18.4.1 Collapsing Cores and Cavities .....	480
18.4.2 Unscrewing Chuck .....	480
<b>19 Ultrasonic Welding</b> .....	481
19.1 Advantages and Disadvantages of Ultrasonic Welding .....	481
19.1.1 Advantages .....	481
19.1.2 Disadvantages .....	482
19.2 General Applications .....	483
19.3 The Principle of Ultrasonic Welding .....	483
19.4 Materials for Ultrasonic Welding .....	484
19.4.1 Additives and Contaminants .....	487
19.4.1.1 Colorants .....	487
19.4.1.2 Fillers, Extenders, and Fibrous Reinforcements .....	487
19.4.1.3 Flame Retardants .....	489
19.4.1.4 Foaming Agents .....	489
19.4.1.5 Impact Modifiers .....	489
19.4.1.6 Lubricants .....	489
19.4.1.7 Mold Releases .....	489
19.4.1.8 Painted Parts .....	490
19.4.1.9 Plasticizers .....	490
19.4.1.10 Regrind .....	490
19.5 Part Design for Ultrasonic Welding .....	490
19.5.1 Overall Ultrasonic Welding Considerations .....	490
19.5.1.1 Strength Requirements .....	491
19.5.1.2 Appearance Requirements .....	491

19.5.1.3 Rigidity Considerations .....	491
19.5.2 Joint Fundamentals .....	494
19.5.2.1 Part Alignment.....	494
19.5.2.2 Uniform Vibration Travel Distance .....	494
19.5.2.3 Minimal Initial Contact Area.....	495
19.5.3 Energy Director Joints .....	496
19.5.3.1 Butt Joint .....	496
19.5.3.2 Joint Layout.....	498
19.5.3.3 Textured Surface .....	500
19.5.3.4 Step Joint.....	500
19.5.3.5 Tongue-and-Groove Joint.....	501
19.5.3.6 Thin-Walled Joint.....	502
19.5.4 Shear Joints.....	502
19.5.5 Hermetic Seals.....	506
19.5.6 Scan Welding.....	506
19.5.7 Stud Welding, Staking, Swaging, and Spot Welding .....	508
19.5.7.1 Staking and Swaging.....	508
19.5.7.2 Stud Welding.....	508
19.5.7.3 Spot Welding.....	512
19.6 Fabric and Film Sealing.....	513
19.7 The Ultrasonic Equipment.....	515
19.7.1 The Basic Principles .....	515
19.7.2 The Power Supply or Generator .....	516
19.7.3 The Converter or Transducer.....	517
19.7.4 The Booster.....	517
19.7.5 The Horn.....	517
19.7.6 The Fixture.....	519
19.7.7 The Controls .....	520
19.7.8 Equipment Frequency.....	521
19.7.9 Automation of Ultrasonic Welding.....	523
19.8 Sources.....	523
<b>20 Vibration Welding .....</b>	<b>524</b>
20.1 Advantages and Disadvantages .....	524
20.1.1 Comparison with Ultrasonic Welding .....	524
20.1.2 Advantages of Vibration Welding.....	524
20.1.3 Disadvantages of Vibration Welding.....	525
20.2 The Process of Vibration Welding .....	526
20.2.1 Linear Vibration Welding.....	528
20.2.2 Orbital Vibration Welding.....	528
20.2.3 Angular Vibration Welding.....	529
20.3 Materials .....	529
20.4 Vibration Welding Part Design .....	532
20.4.1 Basic Considerations.....	532
20.4.2 Joint Designs for Linear Vibration Welding.....	533
20.5 The Equipment.....	536
20.6 Sources.....	537

<b>21 Welding with Lasers</b> .....	538
21.1 Advantages and Disadvantages .....	538
21.1.1 Non-Contact, Surface, Direct, or Butt Laser Welding .....	538
21.1.2 Laser Staking .....	539
21.1.3 Through Transmission Infra-Red Laser Welding .....	539
21.1.4 Advantages of Through Transmission Laser Welding .....	540
21.1.5 Disadvantages of Through Transmission Laser Welding .....	542
21.2 The Process of Laser Welding .....	542
21.2.1 The Laser .....	542
21.2.2 Basic Through Transmission Laser Welding Methods .....	544
21.2.3 Spot or Contour Welding .....	545
21.2.4 Simultaneous Through Transmission Infra-Red (STTIr) Laser Welding (Also Known as Simultaneous Line or Flash Welding) .....	547
21.2.5 Quasi-Simultaneous Laser Welding .....	548
21.2.6 Mask Welding (Leister Patented Process) .....	549
21.3 Materials for Laser Welding .....	550
21.3.1 Material Properties Affecting Laser Weldability .....	550
21.3.2 Effects of Refraction Properties on Material Selection .....	552
21.3.3 Effects of Pigments, Fillers, and Additives on Light Transmission .....	553
21.3.4 Laser Welding Transmitting Materials .....	554
21.3.5 Compatibility of Plastics for Laser Welding .....	556
21.4 Joint Designs .....	556
21.5 Equipment .....	558
21.6 Applications .....	559
21.7 Sources .....	560
 <b>References</b> .....	 561
 <b>Index</b> .....	 568